

Flanschmutter 6 Löcher FM12 (Maße in mm)

Zeichnungsnummer	Rohling	Material	d1 Gewinde	d1±0,2	d2±0,2	d3±0,2	d4 (6x)	a-0,4	b	f1	f2	f3	r1
13515.20-02	12402.00-05R	POM	SG12x7P3,5 RH	18	38	28	4,3	18	6	0,25x45°	0,25x45°	1x45°	0,4
13515.20-04	12402.00-00R	MS	"	"	"	"	"	"	"	"	"	"	"
13508.20-02	12402.00-05R	POM	SG12x9P3 RH	"	"	"	"	"	"	"	"	"	"
13508.20-04	12402.00-00R	MS	"	"	"	"	"	"	"	"	"	"	"
13024.20-02	12402.00-05R	POM	SG12x12P4 RH	"	"	"	"	"	"	"	"	"	"
13024.20-04	12402.00-00R	MS	"	"	"	"	"	"	"	"	"	"	"
13029.20-02	12402.00-05R	POM	SG12x16P4 RH	"	"	"	"	"	"	"	"	"	"
13029.20-04	12402.00-00R	MS	"	"	"	"	"	"	"	"	"	"	"
13517.20-12	12402.00-00R	MS	"	"	"	"	"	"	"	"	"	"	"
13518.20-02	12402.00-05R	POM	SG12x100P8,3 RH	"	"	"	"	"	"	"	"	"	"
13518.20-04	12402.00-00R	MS	"	"	"	"	"	"	"	"	"	"	"

Tabelle neu 24.02.14

13517.20-10 entfernt

Flanschmutter 6 Löcher FM12 (Maße in mm)

Zeichnungsnummer	Rohling	Material	d1 Gewinde	d1±0,2	d2±0,2	d3±0,2	d4 (6x)	a-0,4	b	f1	f2	f3	r1
13515.20-02	12402.00-05R	POM	SG12x7P3,5 RH	18	38	28	4,3	18	6	0,25x45°	0,25x45°	1x45°	0,4
13515.20-04	12402.00-00R	MS	"	"	"	"	"	"	"	"	"	"	"
13508.20-02	12402.00-05R	POM	SG12x9P3 RH	"	"	"	"	"	"	"	"	"	"
13508.20-04	12402.00-00R	MS	"	"	"	"	"	"	"	"	"	"	"
13024.20-02	12402.00-05R	POM	SG12x12P4 RH	"	"	"	"	"	"	"	"	"	"
13024.20-04	12402.00-00R	MS	"	"	"	"	"	"	"	"	"	"	"
13029.20-02	12402.00-05R	POM	SG12x16P4 RH	"	"	"	"	"	"	"	"	"	"
13029.20-04	12402.00-00R	MS	"	"	"	"	"	"	"	"	"	"	"
13517.20-10	12402.00-05R	POM	SG12x30P6 RH	"	"	"	"	"	"	"	"	"	"
13517.20-12	12402.00-00R	MS	"	"	"	"	"	"	"	"	"	"	"
13518.20-02	12402.00-05R	POM	SG12x100P8,3 RH	"	"	"	"	"	"	"	"	"	"
13518.20-04	12402.00-00R	MS	"	"	"	"	"	"	"	"	"	"	"

Tabelle alt